

Fraction to Decimal Conversion Chart

	1/64	.015625
	1/32	.03125
	3/64	.046875
1/16		.0625
	5/64	.078125
	3/32	.09375
	7/64	.109375
1/8		.125
	9/64	.140625
	5/32	.15625
	11/64	.171875
3/16		.1875
	13/64	.203125
	7/32	.21875
	15/64	.234375
1/4		.25
	17/64	.265625
	9/32	.28125
	19/64	.296875
5/16		.3125
	21/64	.328125
	11/32	.34375
	23/64	.359375
3/8		.375
	25/64	.390625
	13/32	.40625
	27/64	.421875
7/16		.4375
	29/64	.453125
	15/32	.46875
	31/64	.484375
1/2		.5
	33/64	.515625
	17/32	.53125
	35/64	.546875
9/16		.5625
	37/64	.578125
	19/32	.59375
	39/64	.609375

5/8		.625
	41/64	.640625
	21/32	.65625
	43/64	.671875
11/16		.6875
	45/64	.703125
	23/32	.71875
	47/64	.734375
3/4		.75
	49/64	.765625
	25/32	.78125
	51/64	.796875
13/16		.8125
	53/64	.828125
	27/32	.84375
	55/64	.859375
7/8		.875
	57/64	.890625
	29/32	.90625
	59/64	.921875
	15/16	.9375
	61/64	.953125
	31/32	.96875
	63/64	.984375
1		1.0

Picas / Points / Inches

1 pica	=	12 points
6 picas	=	1 inch
1 point	=	.138 inch
72 point	=	1 inch

